



FIN: W1V 907635 1P 244158

Current advice for the vehicle:

none

Outstanding KDM:

none

ESKULAB decisions:

none

Damage history:

Typ	Rep. Date	X	#	Damage code	Damage code description	Claim No.	L-KZ	Area	LL	M	E C	Credit note no.	Credit note date
	13.05.2026	AA	20	027906168	23V2790616	21153755	D	24801	173396	km	1	000001415	19.06.2026
	25.02.2026				Service minor	11-259774	D	24801	173394	km			
	17.06.2024				Service minor - VNF - Mileage exceeded	202400526	D	V0000	113808	km			
	27.01.2023	AB	19	014502737	NOx sensor downstream of catalytic converter Electrical fault	330340	D	04830	70570	km	1	000001241	17.02.2023
	27.01.2023	AB	18	014502PR8	NOx sensor downstream of catalytic converter Breakdown service, general documentation	330340	D	04830	70570	km	1	000001241	17.02.2023
	18.01.2023		17	043A08737	Rpm sensor, left, front axle Electrical fault	330228	D	04830	67149	km	1	000001238	27.01.2023
	19.12.2022	AA	16	027906118	22V2790611	056947	D	04830	66578	km	1	000001239	03.02.2023
	15.12.2022		15	003201A31	Connecting rod Warped	056946	D	04830	66577	km	22	000001238	27.01.2023
	15.12.2022		14	050930058	VS3LADKOO	320928	D	04830	66577	km	1	000001238	27.01.2023
	15.12.2022	AA	13	027906148	22V2790614	320928	D	04830	66577	km	3	000001238	27.01.2023
	20.07.2022		12	054963198	VS3KOMRUE	318883	D	04830	56191	km	0	000000000	29.07.2022
	08.06.2022		11	054201908	Instrument cluster Software status	21154862	D	24801	55918	km	0	000000000	08.07.2022
	08.06.2022				Service minor - Regular service	172781	D	24801	55917	km			
	04.03.2022		10	015032737	Glow plug Electrical fault	21152941	D	24801	49277	km	0	000000000	06.05.2022
	04.03.2022		9	054581737	Control unit, diesel engine Electrical fault	21152941	D	24801	49277	km	0	000000000	06.05.2022
	04.03.2022		8	021105008	??? Special regulation	21153443	D	24801	49277	km	0	000000000	27.05.2022
	04.03.2022	AC	7	059013747	K/Z*, injection nozzle, diesel engine Contact fault/open circuit	21153443	D	24801	49277	km	0	000000000	27.05.2022
	04.03.2022	AC	6	059013M18	K/Z*, injection nozzle, diesel engine Replacement vehicle, repair scope > 24 WU	21153443	D	24801	49277	km	0	000000000	27.05.2022
	28.12.2020		5	065300047	Roof paneling, center 1 Leaks	21150556	D	24801	16675	km	0	000000000	29.01.2021
	09.09.2020	AD	4	042341937	Brake lining, parking brake Burnt/carbonized	21156557	D	24801	7320	km	0	000000000	23.10.2020



Vehicle Information (Damage history)

52602

Typ	Rep. Date	X	#	Damage code	Damage code description	Claim No.	L-KZ	Area	LL	M	E C	Credit note no.	Credit note date
	09.09.2020	AD	3	042341M18	Brake lining, parking brake Replacement vehicle, repair scope > 24 WU	21156557	D	24801	7320	km	0	000000000	18.09.2020
	09.09.2020		2	081A0G388	Cover, mirror triangle, left Loose	21156557	D	24801	7320	km	0	000000000	18.09.2020
	09.09.2020		1	042343**7	Expanding lock, parking brake **	21157836	D	24801	7320	km	0	000000000	04.12.2020